

Firmware Update VSX-LX303 and VSX-LX503 (09-23-2020)

We are pleased to offer this firmware update for the best possible performance of your AV Receiver.

This update may be installed via USB or Network. We recommend USB for faster, more reliable installation.

**VSX-LX303, VSX-LX503
(Current Version 1081-1000-1060-0011)**

The 09/23/2020 update will address the following and includes previous updates:

1. Improve reception capability in certain TuneIn Radio stations.
2. Fix the issue of Bluetooth connection with certain devices.
3. Fix the issue that start tuning operation when pressing UP/DOWN cursor at TUNER selector.
4. Improve the stability of operation when returning from Network Standby.

Previous Updates:

The 02/06/2020 update will address the following and includes previous updates:

1. Improve the list viewing for "Albums/ Artists/ Songs" in My Music of Amazon Music.
*Service of Amazon Music may vary by country.
2. Correct "the unstable elapsed time" and "no album art" when playback through Music Server or USB.

Version 1070-9000-1060-0011

- Update Chromecast built-in version to 1.36.
- Improve search performance of music server.

- Improve playback stability for FLAC files.

Version 1060-8000-1050-0010

- Improve playback stability for Chromecast Built-in.
- Improve playback stability for Airplay.
- Improve the playability for certain WAV files.

Version 1060-7000-1050-0010

- Support AirPlay2.
- Add setting to switch "Standard" and "Enhanced" according to HDMI 4K signal format.
- https://jp.pioneer-audiovisual.com/manual/sup/upd/hdmi_4k_pio.pdf
- Minor bug fixes and improvements stability.

Version 1050-6000-1040-0010

- Minor bug fixes and improvements stability.

Version 1040-5000-1040-0010

- Adds support for Amazon Music.
Amazon Music service requires that you have Amazon Prime account or Amazon Music Unlimited account
Pioneer Remote App is required for initial set-up of Amazon Music.
For detail about updated function, please refer to the link below.
http://jp.pioneer-audiovisual.com/manual/sup/upd/amazon_pio.pdf
- (VSX-LX503) Adds support for eARC.
HDMI cable needs to be Ethernet-enabled HDMI cable.
For detail about updated function, please refer to the link below.
http://jp.pioneer-audiovisual.com/manual/sup/upd/earc_pio.pdf
- Adds setting of Preset Volume for Sonos Connect.
For detail about updated function, please refer to the link below. http://jp.pioneer-audiovisual.com/manual/sup/upd/sonosconnect_pio.pdf
- Enhanced security.
Depending on the Firmware version, update will be needed 2 times.
- Minor bug fixes and improvements stability.

Version 1030-4000-0030-0010

- Enhanced security.
- Adds support for Deezer HiFi.
- Depending on the Firmware version, update will be needed 2 times.

Version 1020-3000-0030-0010

- Adds support for Sonos Connect.
For detail about updated function, please refer to the link below.

http://jp.pioneer-audiovisual.com/manual/sup/upd/sonosconnect_pio.pdf

- Minor bug fixes and improvements stability.

Firmware Update Instructions

Update the firmware via network or USB connection.

"Updating the firmware via network"

You can update the firmware by connecting the unit to a network.

"Updating the firmware via USB connection"

You need a 128 MB or larger capacity USB storage for updating.

For details, see "Firmware Update" of the Instruction Manual.