

Firmware Update VSX-934, VSX-LX104 (09-23-2020)

We are pleased to offer this firmware update for the best possible performance of your Elite AV Receiver.

This update may be installed via USB or Network. We recommend USB for faster, more reliable installation.

**VSX-934, VSX-LX104
(Current Version 1030-6010-1020-0010)**

The 09/23/2020 update will address the following and includes previous updates:

1. Improve reception capability in certain TuneIn Radio stations.
2. Fix the issue of Bluetooth connection with certain devices.
3. Fix the issue that start tuning operation when pressing UP/DOWN cursor at TUNER selector.
4. Improve the stability of operation when returning from Network Standby.

Previous Updates:

The 02/06/2020 update will address the following and includes previous updates:

1. Improve the list viewing for "Albums/ Artists/ Songs" in My Music of Amazon Music.
*Service of Amazon Music may vary by country.

Previous Updates:

Version 1030-4010-1020-0010

- Improve the playability for certain WAV files.
- Improve playback stability for FLAC files.

Version 1020-3010-1010-0010

- Support Dolby Atmos Height Virtualizer.*

- Support DTS Virtual:X.*

*For more detail please refer to "Listening Mode Effects" in the instruction manual

- Improve streaming ability of the particular DSD file (dff).

- Fix the issue that cannot display album art in the certain FLAC file.

- Change maximum volume level of Personal Preset as default from -32dB to 0dB.

Version 1010-2000-0000-0010

-Minor bug fixes and improvements stability.

Version 1010-1000-0000-0010

- Support AirPlay2.

- Add setting to switch "Standard" and "Enhanced" according to HDMI 4K signal format.

For detail about updated function, please refer to the link below.

https://jp.pioneer-audiovisual.com/manual/vsx934/supple_934.pdf

-Minor bug fixes and improvements stability.

Firmware Update Instructions

Update the firmware via network or USB connection.

"Updating the firmware via network"

You can update the firmware by connecting the unit to a network.

"Updating the firmware via USB connection"

You need a 128 MB or larger capacity USB storage for updating.

For details, see "Firmware Update" of the Instruction Manual.