

# **Firmware Update Elite VSX-LX304, VSX-LX504 (12-22-2020)**

We are pleased to offer this firmware update for the best possible performance of your Elite AV Receiver.

**This update may be installed via USB or Network.**

**VSX-LX304, VSX-LX504  
(Current Version R122-0708-1141-0029)**

**The 12/22/2020 update will address the following:**

1. Update Chromecast built-in version to 1.44.
2. Support ALLM "Auto Low Latency Mode".
3. Fix the issue that cannot display the logo of certain TuneIn Radio stations.
4. Improve reception capability in certain TuneIn Radio stations.

## **Previous Updates:**

**The 10/28/2020 update will address the following:**

1. Enhance network security.

"username" and "password" will be required to use Web Setup feature after this update. \*

\*Please refer to the link below for more details. [https://jp.pioneer-audiovisual.com/manual/sup/upd/websetup\\_pio.pdf](https://jp.pioneer-audiovisual.com/manual/sup/upd/websetup_pio.pdf)

2. Change login method of TIDAL for enhancing security.\* \*Please refer to the link below for more details. [https://jp.pioneer-audiovisual.com/manual/sup/upd/tidal\\_pio.pdf](https://jp.pioneer-audiovisual.com/manual/sup/upd/tidal_pio.pdf)

3. Add "Center Spread" setting for Dolby signals.\*  
\*Please refer to the link below for more details. [https://jp.pioneer-audiovisual.com/manual/sup/upd/centerspread\\_pio.pdf](https://jp.pioneer-audiovisual.com/manual/sup/upd/centerspread_pio.pdf)

4. Minor bug fixes and improvements stability.

**The 03/12/2020 update will address the following**

1. Support "Volume Pass Through" mode for Sonos.\*

\*For detail about updated function, please refer to the link below.  
[https://jp.pioneer-audiovisual.com/manual/vsx934/supple\\_934.pdf](https://jp.pioneer-audiovisual.com/manual/vsx934/supple_934.pdf)

2. Update Chromecast built-in version to 1.40.
3. Improve the list viewing for "Albums/ Artists/ Songs" in My Music of Amazon Music.

4. Fix the issue of Bluetooth connection with certain iOS devices.

Version R113-0304-1131-0026

-Support 'Works with Alexa'.\*

-Support control of multiple Sonos Connect.\*

"\*For detail about updated function, please refer to the link below.

LX304/504: [https://jp.pioneer-audiovisual.com/manual/vsx934/supple\\_934.pdf](https://jp.pioneer-audiovisual.com/manual/vsx934/supple_934.pdf)

-Minor bug fixes and improvements stability.

Version R109-0203-1021-0026

-Support IMAX Enhanced.\*

-Support Dolby Atmos Height Virtualizer.\*

"\*For detail about updated function, please refer to the link below.

[https://jp.pioneer-audiovisual.com/manual/vsx934/supple\\_934.pdf](https://jp.pioneer-audiovisual.com/manual/vsx934/supple_934.pdf)"

-Update Chromecast built-in version to 1.36.

-Improve playback stability for FLAC files.

-Change maximum volume level of Personal Preset as default from -32dB to 0dB.

Version R103-0102-0000-0024

-Minor bug fixes and improvements stability.

Version

- Support AirPlay2.

- Add setting to switch "Standard" and "Enhanced" according to HDMI 4K signal format.

-Minor bug fixes and improvements stability.

## **Firmware Update Instructions**

Update the firmware via network or USB connection.

"Updating the firmware via network"

You can update the firmware by connecting the unit to a network.

"Updating the firmware via USB connection"

You need a 128 MB or larger capacity USB storage for updating.

For details, see "Firmware Update" of the Instruction Manual.