Firmware Update UDP-LX500 (12-17-2019)

We are pleased to offer this firmware update for the best possible performance of your BD Player**.**

This update may be installed via USB or Network.
We recommend USB for faster, more reliable installation.

UDP-LX500
(Current Version V01.16)

The 12-17-2019 update will address the following and includes previous updates:

1. Improve playback compatibility of certain 4K UHD Blu-ray discs.

Previous Updates:

Version V01.13
- Improve playback compatibility of certain 4K UHD Blu-ray discs.

Version V01.12
- Improve stability of playback for, BD-R/RE and SACD.
- Improve stability of playback web content.
- Minor bug fixes and stability improvements.

Version V01.08
- Minor bug fixes and improvements stability.

Firmware Update Instructions

Software updating

The player's software can be updated using one of

the methods shown below.
• Connecting to the Internet….**Currently, the update via network is temporary unavailable due to maintenance.**
• Using a USB flash drive.

Please visit page 47 of the Operating Instructions for details
.