

Firmware Update VSX-934, VSX-LX104 (02-02-2022)

We are pleased to offer this firmware update for the best possible performance of your AV Receiver.

This update may be installed via USB or Network.

VSX-934, VSX-LX104

(Current Version 1041-0010-1020-0010)

The 02/02/2022 update will address the following:

1. Minor bug fixes and improvements stability.

Previous Updates:

The 11/24/2021 update will address the following:

1. Fix the playback format issue converted as AAC format while playing TIDAL's FLAC audio format.
2. Improve reception capability in certain TuneIn Radio stations.
3. Minor bug fixes and improvements stability.

The 06/30/2021 update will address the following:

1. Increase the upper limit of connectable SONOS device from 8 to 32.

The 01/14/2021 update will address the following:

1. Change login method of TIDAL for enhancing security.*

*Please refer to the link below for more details.

https://www.onkyo.com/manual/sup/upd/tidal_onk.pdf

2. Fix the issue that cannot display the logo of certain TuneIn Radio stations.
3. Improve reception capability in certain TuneIn Radio stations.
4. Minor bug fixes and improvements stability.

The 09/23/2020 update will address the following :

1. Improve reception capability in certain TuneIn Radio stations.
2. Fix the issue of Bluetooth connection with certain devices.
3. Fix the issue that start tuning operation when pressing UP/DOWN cursor at TUNER selector.

4. Improve the stability of operation when returning from Network Standby.

The 02/06/2020 update will address the following and includes previous updates:

1. Improve the list viewing for "Albums/ Artists/ Songs" in My Music of Amazon Music.

*Service of Amazon Music may vary by country.

Previous Updates:

Version 1030-4010-1020-0010

- Improve the playability for certain WAV files.
- Improve playback stability for FLAC files.

Version 1020-3010-1010-0010

- Support Dolby Atmos Height Virtualizer.*

- Support DTS Virtual:X.*

*For more detail please refer to "Listening Mode Effects" in the instruction manual

- Improve streaming ability of the particular DSD file (dff).

- Fix the issue that cannot display album art in the certain FLAC file.

- Change maximum volume level of Personal Preset as default from -32dB to 0dB.

Version 1010-2000-0000-0010

-Minor bug fixes and improvements stability.

Version 1010-1000-0000-0010

- Support AirPlay2.

- Add setting to switch "Standard" and "Enhanced" according to HDMI 4K signal format.

For detail about updated function, please refer to the link below.

https://jp.pioneer-audiovisual.com/manual/vsx934/supple_934.pdf -

Minor bug fixes and improvements stability.

Firmware Update Instructions

Update the firmware via network or USB connection.

"Updating the firmware via network"

You can update the firmware by connecting the unit to a network.

"Updating the firmware via USB connection"

You need a 128 MB or larger capacity USB storage for updating.

For details, see "Firmware Update" of the Instruction Manual.