

## **Firmware Update SC-LX501 (02-06-2020)**

We are pleased to offer this firmware update for the best possible performance of your AV Receiver.

**This update may be installed via USB or Network. We recommend USB for faster, more reliable installation.**

**SC-LX501  
(Current Version **2150-3040-5080-0011**)**

**The 02/06/2020 update will address the following and includes previous updates:**

- 1. Improve the list viewing for "Albums/ Artists/ Songs" in My Music of Amazon Music.  
\*Service of Amazon Music may vary by country.**
- 2. Correct "the unstable elapsed time" and "no album art" when playback through Music Server or USB.**

### **Previous Updates:**

Version 2150-2040-5080-0011

- Update Chromecast built-in version to 1.36.
- Improve search performance of music server.
- Improve playback stability for FLAC files.

Version 2140-1040-5070-0010

- Improve playback stability for Chromecast Built-in.
- Improve playback stability for Airplay.
- Improve the playability for certain WAV files.

Version 2140-0040-5070-0010

- Minor bug fixes and improvements stability.

#### Version 2139-9040-5070-0010

- Minor bug fixes and improvements stability.

#### Version 2139-8040-5070-0010

- Enhanced security.  
Depending on the Firmware version, update will be needed 2 times.
- Minor bug fixes and improvements stability.

#### Version 2129-7040-5070-0010

- Enhanced security.
- Adds support for Deezer HiFi.

#### Version 2119-6040-5070-0010

- Improvement of audio output when playback certain Dolby Digital Plus contents.
- Minor bug fixes and improvements stability.

#### Version 2109-5030-5060-0008

- Improve the noise during playback via USB/Network

#### Version 2109-4030-5060-0008

- Adds support of external audio inputs\* for "FlareConnect".
- \*For detail about external audio inputs, please refer to the link below.  
<http://pioneer-audiovisual.com/flareconnect/>
- Minor bug fixes and improvements stability.

#### Version 2099-3030-5050-0008

- Adds support for pass-through function of Dolby Vision signal.
- When set up "HDMI Out" to "MAIN+SUB", the Dolby Vision video is available from only HDMI OUT MAIN terminal.
- This particular firmware update is only available via USB installation.

#### Version 2089-3030-4040-0008

- Adds support for new multi-room audio playback function "FlareConnect".  
\*All audio devices in group and "Pioneer Remote" App is required to update to the latest version.

#### How to Enjoy FlareConnect

<http://intl.pioneer-audiovisual.com/letthemusicplay/setup>

#### Introduction of multi-room audio functions

?<http://intl.pioneer-audiovisual.com/letthemusicplay/>

- Minor bug fixes and improvements stability.

#### Version 2079-2030-3030-0008

- Expand playable content of DTS:X.
- Adds "Play Queue" function.  
For detail about updated function, please refer to the link below.  
[http://jp.pioneer-audiovisual.com/manual/sup/upd/queue\\_pio.pdf](http://jp.pioneer-audiovisual.com/manual/sup/upd/queue_pio.pdf)
- Adds "Search/ Sort" function on Music server.
- Adds "Display WAV file information ( album art, artist, album ) via USB" function.

Please note that only above functions are added this time. Please refer to the link below and find out the explanation of your related function.

[http://jp.pioneer-audiovisual.com/manual/sup/upd/audio1709\\_na\\_pio.pdf](http://jp.pioneer-audiovisual.com/manual/sup/upd/audio1709_na_pio.pdf)

Important notice: \* The fore mentioned functions depend on model - not all functions are available for each model.

- Minor bug fixes and performance improvements.

#### Version 2069-0020-2020-0008

- Adds support for Chromecast built-in.  
\*Chromecast-enabled applications is required to enjoy Chromecast built-in.  
\*As an initial setting, before starting to use Chromecast built-in, you need to accept the PRIVACY POLICY on our

smartphone application "Pioneer Remote App".

For more detailed information, Please refer to below.

[http://jp.pioneer-audiovisual.com/manual/sup/upd/chromecast\\_pio.pdf](http://jp.pioneer-audiovisual.com/manual/sup/upd/chromecast_pio.pdf)

- Minor bug fixes and performance improvements.

Note:

If Bluetooth devices were previously paired, you must pair the devices again after the Firmware update is complete.

Version 2001-0010-2020-0001

- Adds support for FireConnect.

This update will enable streaming from Network Services/USB/Bluetooth/Music server.

\*Sampling rates of 44.1 kHz and 48 kHz are supported.(USB/Music server).

\*Pioneer Remote App is required to enjoy FireConnect.

How to Enjoy FireConnect?F

<http://intl.pioneer-audiovisual.com/letthemusicplay/setup/fireconnect.pdf>

Introduction of multi-room audio functions?F

<http://intl.pioneer-audiovisual.com/letthemusicplay/>

- Minor bug fixes and performance improvements.

Note:

If Bluetooth devices were previously paired, you must pair the devices again after the Firmware update is complete.

Version 1020-2010-1101-0000

- Support DTS:X

- Support TIDAL

- Support Deezer

- Other improvement.

Note:

If you have already done the Full Auto MCACC, you need to re-calibrate after update.

Availability of TIDAL and Deezer services will differ by region.

## **Firmware Update Instructions**

Update the firmware via network or USB connection.

"Updating the firmware via network"

You can update the firmware by connecting the unit to a network.

"Updating the firmware via USB connection"

You need a 128 MB or larger capacity USB storage for updating.

For details, see "Firmware Update" of the Instruction Manual.