

Firmware Update Pioneer SCLX701/801/901 (02-02-2022)

We are pleased to offer this firmware update for the best possible performance of your Pioneer AV Receiver.

This update may be installed via USB or Network.

SC-LX701/801/901

(Current Version 2190-7000-5080-0011)

The 02/02/2022 update will address the following:

1. Minor bug fixes and improvements stability.

Previous Updates:

The 11/24/2021 update will address the following:

1. Increase the upper limit of connectable SONOS device from 8 to 32.
2. Fix the playback format issue converted as AAC format while playing TIDAL's FLAC audio format.
3. Improve reception capability in certain TuneIn Radio stations.
4. Minor bug fixes and improvements stability.

The 01/14/2021 update will address the following:

1. Change login method of TIDAL for enhancing security.*

*Please refer to the link below for more details.

https://jp.pioneer-audiovisual.com/manual/sup/upd/tidal_pio.pdf

2. Fix the issue that cannot display the logo of certain TuneIn Radio stations.
3. Improve reception capability in certain TuneIn Radio stations.

Minor bug fixes and improvements stability

The 09/23/2020 update will address the following :

1. Improve reception capability in certain TuneIn Radio stations.
2. Fix the issue of Bluetooth connection with certain devices.
3. Fix the issue that start tuning operation when pressing UP/DOWN cursor at TUNER selector.
4. Improve the stability of operation when returning from Network Standby.

The 02/06/2020 update will address the following and includes previous updates:

1. Improve the list viewing for "Albums/ Artists/ Songs" in My Music of Amazon Music.
*Service of Amazon Music may vary by country.
2. Correct "the unstable elapsed time" and "no album art" when playback through Music Server or USB.

The 11/14/2019 update will address the following and includes previous updates:

1. Update Chromecast built-in version to 1.36.
2. Improve search performance of music server.
3. Improve playback stability for FLAC files.

The 7/4/2019 update will address the following and include previous updates:

1. Improve playback stability for Chromecast Built-in.
2. Improve the playability for certain WAV files.

Firmware Update Instructions:

Update the firmware via network or USB connection. "Updating the firmware via network" You can update the firmware by connecting the unit to a network. "Updating the firmware via USB connection" You need a 128 MB or larger capacity USB storage for updating. For details, see "Firmware Update" of the Instruction Manual.