

Firmware Update Elite VSX-LX304, VSX-LX504 (08-04-2020)

We are pleased to offer this firmware update for the best possible performance of your Elite AV Receiver.

**This update may be installed via USB or Network.
We recommend USB for faster, more reliable
installation.**

**VSX-LX304, VSX-LX504
(Current Version **R117-0506-1131-0028**)**

The 08/04/2020 update will address the following:

1. Support "Critical Listening mode of DTS Play-Fi"
2. Unlock IP/Serial/IR/Front Panel volume controls if using Sonos "Volume Pass-Through" feature
3. Minor bug fixes and improvements stability.

Previous Updates:

The 03/12/2020 update will address the following:

1. Support "Volume Pass Through" mode for Sonos.*

*For detail about updated function, please refer to the link below.
https://jp.pioneer-audiovisual.com/manual/vsx934/supple_934.pdf

2. Update Chromecast built-in version to 1.40.
3. Improve the list viewing for "Albums/ Artists/ Songs" in My Music of Amazon Music.
4. Fix the issue of Bluetooth connection with certain iOS devices.

The 03/12/2020 update will address the following:

-Support 'Works with Alexa'.*

-Support control of multiple Sonos Connect.*

**For detail about updated function, please refer to the link below.

LX304/504: https://jp.pioneer-audiovisual.com/manual/vsx934/supple_934.pdf

-Minor bug fixes and improvements stability.

The 5/29/2019 update will address the following:

-Support IMAX Enhanced.*

-Support Dolby Atmos Height Virtualizer.*

"*For detail about updated function, please refer to the link below.

https://jp.pioneer-audiovisual.com/manual/vsx934/supple_934.pdf"

-Update Chromecast built-in version to 1.36.

-Improve playback stability for FLAC files.

-Change maximum volume level of Personal Preset as default from
- 32dB to 0dB.

The 5/29/2019 update will address the following:

-Minor bug fixes and improvements stability.

Version

- Support AirPlay2.

- Add setting to switch "Standard" and "Enhanced" according to HDMI 4K signal format.

-Minor bug fixes and improvements stability.

Firmware Update Instructions

Update the firmware via network or USB connection.

"Updating the firmware via network"

You can update the firmware by connecting the unit to a network.

"Updating the firmware via USB connection"

You need a 128 MB or larger capacity USB storage for updating.

For details, see "Firmware Update" of the Instruction Manual.